

**TOWN OF SUPERIOR  
RESOLUTION NO. R-41  
SERIES 2019**

**A RESOLUTION OF THE BOARD OF TRUSTEES OF THE TOWN OF  
SUPERIOR REDUCING THE SPEED LIMIT ALONG SOUTH COAL  
CREEK DRIVE FROM 35 MILES PER HOUR TO 25 MILES PER  
HOUR**

**WHEREAS**, South Coal Creek Drive was built in the early 1990s as a major collector with a posted speed of 35 miles per hour north of Rock Creek Parkway;

**WHEREAS**, in April 2019, the Superior Public Works & Utilities Department conducted a traffic survey of South Coal Creek Drive to determine the impacts of the current posted speed limit and whether a reduction in speed limit on South Coal Creek Drive is warranted as part of the implementation of the 2014 Superior Transportation Plan;

**WHEREAS**, the survey considered the road characteristics, current and future development, environmental factors, parking practices, pedestrian and bicycle activity in the vicinity, and crash statistics from the most recent year; and

**WHEREAS**, the Board of Trustees has reviewed the survey and finds it in the best interest of the public health, safety and welfare to reduce the maximum speed limit from 35 miles per hour to 25 miles per hour on South Coal Creek Drive.

**NOW, THEREFORE, BE IT RESOLVED BY THE BOARD OF TRUSTEES OF THE TOWN OF SUPERIOR, COLORADO, as follows:**

**Section 1.** The Board of Trustees hereby reduces the speed limit along South Coal Creek Drive north of Rock Creek Parkway from 35 miles per hour to 25 miles per hour.

**Section 2.** Pursuant to C.R.S. § 42-4-1102(2), the change in speed limit contemplated herein will be effective when appropriate signs giving notice of this change are erected upon the impacted portions of South Coal Creek Drive.

ADOPTED this 8<sup>th</sup> day of July, 2019.

Clint Folsom  
Clint Folsom, Mayor

ATTEST:

Phyllis E. Hardin  
Phyllis E. Hardin, Town Clerk-Treasurer

The seal of the Town of Superior, Colorado, is circular with a rope-like border. The text "TOWN OF SUPERIOR" is written along the top inner edge, and "COLORADO" is written along the bottom inner edge. A small star is positioned at the bottom center of the seal.